



Packard **SERVICE TECHNICAL**
Bulletin

56T-9
Dealer 7
February 10, 1956

To: ZONES AND DEALERS

Subject: ULTRAMATIC TRANSMISSION REAR OIL PUMP DRIVER

This article cancels Service Technical Bulletin 55T-47, Dealer 38, dated November 15, 1955.

The rear oil pump driver has been completely redesigned. It is machined to fit snug into the rear oil pump rotor and also pilots on the planetary output shaft.

The new oil pump driver can be used on 54th Series "Gear Start" and 55th and 56th Series Ultramatic transmissions.

It can be ordered under part number 6489292.

Very truly yours,

T. W. Nertney
T. W. Nertney
Service Technical Manager

HGL:mu