

REFER TO THIS LETTER BY NUMBER

# PACKARD MOTOR CAR COMPANY

DETROIT MICHIGAN

May 18, 1929.


To: Packard Distributors

Subject: UNIVERSAL JOINT SHAFT REPAIRS.

TO BE NOTED AND INITIALED BY	

This letter cancels and supersedes Trade Letter No. T-2349, T-2371 and all other letters on this subject.

All Universal Joint Shafts, such as illustrated and identified by any of the numbers listed below which have not been previously repaired and do not show excessive wear at the splines, will hereafter and until further notice be handled by the factory on a credit basis. This credit will be at the current net price less two dollars (\$2.00) for reconditioning.



A notation on your Returned Goods tag to "Credit less repairs" will impart the desired information. Replacement shafts for your stock should be ordered from Factory Service stock in the regular manner. Shafts which have heretofore been repaired and returned to the distributor and now in their stock in good condition will not be credited on this basis and these should not be returned to the factory.

The identity of each shaft to which this arrangement shall apply may be established by its length in inches measuring from the center line of the yoke. Please consult this list and compare part with illustration before shipping.

Piece No.	Length	Name	Models
134325	56"	U. J. Shaft only	243-333
134326	49"	" " "	236-326
139580	58 $\frac{1}{8}$ "	" " "	243-333
139581	51 $\frac{3}{8}$ "	" " "	236-326
141900	57 $\frac{7}{8}$ "	" " "	243-343-333-433
141901	50 $\frac{7}{8}$ "	" " "	236-336-326-426
156315	57 $\frac{5}{8}$ "	" " "	443-533
156316	50 $\frac{5}{8}$ "	" " "	526
164639	48 $\frac{3}{4}$ "	" " "	626
164823	55 $\frac{1}{2}$ "	" " "	633-640
164824	60 $\frac{1}{4}$ "	" " "	645
170204	41 $\frac{1}{2}$ "	" " "	Special

All other joint repairs can and should be performed in your own Service Department. This will enable you to liquidate your stock of universal joint assemblies by working into service repairs most of the detail parts now held in assembled units. Effective immediately, no complete assemblies will be accepted at the Factory for repairs except on a time and material basis, and all such assemblies will be returned after completion of such repairs.

Yours very truly,

PACKARD MOTOR CAR COMPANY

B. R. Horsley  
Manager Service Stores