SPECIAL "SELL MORE PARTS" BULLETIN

ACKARD PARTS for PACKARD CARS



PACKARD SERVICE for PACKARD OWNERS

SERVICE STORES DIVISION

PACKARD MOTOR CAR COMPANY

PACKARD DISTRIBUTERS AND DEALERS

NO. 116

MITENTION General Manager Service Manager Stock Manager DATE Nov. 17, 1933

Motor troubles frequently are traceable to faulty vacuum tanks. It is not always easy to find the difficulty and, even when located, it is not always good economy to attempt corrections.

Why spend your time and your customer's money on an old, worn-out mechanism when a brand new unit can be installed at so small a cost. We have a surplus stock of new, complete vacuum tank assemblies and will ship, as long as they last, for any model on which this equipment was standard. Every service man should have this information on tap at all times. Your customary parts discount applies.

Pc. No.	Name		Models		Sugges Zone 1	ed List Zone 2		
FG. 110.	1100110			and the same of th				-#13
114145	Gasoline	Vacuum	tank asb.	116	\$5. 05	\$5.29	\$5.73	7719
130808		<u></u>	- 11	-1 36-43,226-33			11	#17
133212	ti .	Ħ	11	126-33-36-43, 226-33	11			#19
142714				236-43,236-43, 443				
148029	11	tt	Ħ	443,526-33,626 33-40-45,740-46		*1		
148463	11	j • #	11	443,626-33-40- 726-33-40		***	tt .	
177309	11	11	tr	726-33-40	11	11	11	
177310	ŧŧ	11	11	745	Ħ	tı	11	

Yours very truly,

PACKARD MOTOR CAR COMPANY

B. R. Honley

B. R. Horsley Manager Service Stores